City of Greenbelt, MD

1 of 4

## **Site Photos**

Photo 1: Existing untreated stormwater collection culvert and potential water treatment site. Building in background is the Department of Public Works facility.




Photo 2: Existing park gateway from the parking lot and location for main interpretive signage.



## **Site Photos**

Photos 3 and 4: Existing untreated impervious surface of parking lot. Photo 3 looking down grade toward the Department of Public Works Facility and Photo 4 looking toward Crescent Road from the Recycling Center entrance.





## Site Photos

Photo 5: Existing grades, site layout and untreated stormwater collection facilities.

